

Figure 5. Platform installation at the inlet to Siphon 3 in Pond 3.



*A conductivity probe to measure salinity and a pressure transducer to measure water surface elevation were attached to this staff gauge and connected to a data logger shown in the insert.*

Figure 6. Access platform to upstream canal side of Siphon 5.



*Notice the access shaft to the siphon just behind the canoe. Instrumentation was fixed to these platforms where possible.*